





Product Function

 $\underline{ \text{Used for measuring }} \text{ transformer winding resistance, conductor DC resistance, cable length, etc.} \\$

Product features

- 1.The tester Max output voltage is 24V, Max test current is 10A. It has a fast test speed and can be applied to the measurement of transformers and other resistances.
- 2.There are two measurement modes: automatic measurement mode, which can automatically select the test current based on the load; Manual measurement mode: 6 test current gears can be chose.
- 3.With Bluetooth communication function, user can make the testing operate and view the test result after installing the APP. The tester also equip with USB interface and monitoring software, which can communicate with computer.
- 4. With discharge function, which can automatically discharges after testing.
- 5.With alarm function, can set resistance alarm value. Additionally, the tester has automatic shutdown function, which will automatically shut down after 15 minutes without any operation when the automatic shutdown is set.

Technical Specification

| Power Supply | DC 22.2V 5200mAh rechargeable lithium battery | | |
|-------------------------|---|-----------|--------|
| Measurement Mode | Automatic & Manual | | |
| Display Range | 1.0uΩ~50.00kΩ | | |
| Range & Test Current | 200.0uΩ~50.00kΩ | AUTO | |
| | 200.0uΩ~20.00mΩ | 10A | 0.2%FS |
| | 10.00mΩ~200.0mΩ | 5A | 0.5%FS |
| | 100.0mΩ~2.000Ω | 1A | 1%FS |
| | 1.00Ω~20.00Ω | 100mA | 1%FS |
| | 10.00Ω~200.0Ω | ≤10mA CVT | 1%FS |
| | 100.0Ω~50.00kΩ | ≤1mA CVT | 1%FS |
| Max Resolution | 0.1uΩ | | |
| Measurement Accuracy | 0.2% | | |
| Test Current Gear | 10A, 5A, 1A, 100mA, 10mA, 1mA, AUTO | | |
| Output Voltage | 24V MAX | | |
| Alarm Setting | Alarm critical value setting range; $1m\Omega\sim2500\Omega$, 0Ω is not start the alarm function. Do not active the alarm function every starting up the tester | | |
| Alarm Warning | When the test value exceeds the alarm setting value, the buzzer will have alarm sound prompt | | |
| Low Voltage Indication | When battery voltage drops to DC 22V±0.1V, low battery voltage symbol will display and remind to charge in time | | |
| Data Storage | 600 groups (data will not be lost after power failure or battery replacement) | | |
| Automatic Shutdown | After setting automatic shutdown, 15 minutes without any operation after starting up will automatic shutdown | | |
| LCD Dimension | 128mmX75mm; Display area:124X67mm | | |
| Host Dimension | 280mmX260mmX160mm | | |
| Weight | Total weight: 5.8kg(include all accessories) | | |
| Bluetooth Communication | Yes | | |
| USB Interface | With USB interface, software monitoring, storage data can be uploaded to computer, save and print. | | |
| Withstand Voltage | AC 3700V/rms(between the housing and screws) | | |
| Accessories | Tester: 1PCS; Test line: 2PCS; USB communication cable: 1PCS; Special charger: 1PCS; Tool bag : 1PCS | | |

